

# Featured Project: Culzean Castle, Ayr



## Stone Type: Sandstone

As main contractors for the restoration of the castle, Stirling Stone carried out extensive re-pointing and removal of flaking stonework, conserving as much of the original stone as possible. Badly weathered sections were replaced, including moulded string courses and decorative panels.

The company also carried out extensive stonework repairs and alterations to the Swan Pond building and Hoolity Ha' bridge on the Culzean estate.

